

Palma Sola Trace

Construction Type:

Stucco over masonry condominium buildings.

Challenge

A large-scale 272-unit condominium community requiring exterior repainting, full sealant removal and replacement, and extensive stucco repairs.

Solution:

Removed and replaced all failing sealants to restore a watertight envelope. Performed comprehensive stucco repairs and completed a full exterior repaint to protect the buildings and enhance curb appeal.



Munyan Painting Services